



# SIDEPAK™ AM520

## PERSONAL AEROSOL MONITOR

### QUICK START GUIDE



### Main Menu




1. Install the battery and secure with screws.
2. Charge the battery.





3. Select Impactor and sintered disk (if needed).



4. Power on.



<p><b>5. If using impactors . . . verify 1.7 L/min flow rate with flow calibrator (sold separately).</b></p> 	
<p><b>6. Zero Cal the instrument</b> (Menu   Calibration   Zero Cal . . . and follow on-screen instruction.)</p> 	
<p><b>7. Select Calibration Factor (if needed)</b> (Menu   Calibration   User Cal).</p> <p>Factory default = 1.0, Ambient Aerosol = 0.38, or Custom calibration factor.</p>	
<p><b>8. Select Run Mode</b> (Menu   Survey - Manual - Program).</p> <p><b>Note:</b> Survey Mode does not log data.</p> <p>Programs 1 to 5 are set up in TrakPro™ Data Analysis Software on a computer and imported into the AM520.</p>	

**9. Download logged data to TrakPro™ v5 software** *(sold separately).*

AM520 must be powered “on” to communicate and download data.



UNDERSTANDING, ACCELERATED

**TSI Incorporated** – Visit our website [www.tsi.com](http://www.tsi.com) for more information.

**USA**           Tel: +1 800 874 2811  
**UK**             Tel: +44 149 4 459200  
**France**       Tel: +33 1 41 19 21 99  
**Germany**     Tel: +49 241 523030

**India**           Tel: +91 80 67877200  
**China**          Tel: +86 10 8219 7688  
**Singapore**    Tel: +65 6595 6388

